

# SAFETY RECALL

LaJobi, Inc.

Babi Italia “Pinehurst” and Bonavita “Hudson”  
Drop Side Cribs  
Entrapment and Suffocation Hazards



The lower spring pins on the footboard and headboard can pop out of tracks on the drop side causing drop side detachment from cribs; thereby, creating a hazardous gap between the drop side and crib mattress in which infants and toddlers can become entrapped and suffocate. Pinehurst and Hudson drop side cribs with production dates from **December 2006 through August 2007** are involved in the recall. The production date with other crib information is printed on a label attached to the footboard or headboard.

**Pinehurst Model 3151035(item# 631210) and Model 4051002 (item# 802414)**  
carried exclusively by Babies“R”Us in stores and online at  
[www.babiesrus.com](http://www.babiesrus.com) .

**Hudson Crib Model numbers are 4240101051, 4240101002 and 4240101054**

**CONSUMERS SHOULD IMMEDIATELY STOP USING THE  
RECALLED CRIBS AND CONTACT LAJOBİ TOLL-FREE AT:**

**(866) 688-9009**

or visit the website at

**[www.lajobi.com](http://www.lajobi.com)**

to register to have professional technicians install free retrofit kits within 48 hours.